# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 30982 2-10 Maple Croft Block 2-10, Leeds

#### **Cover Sheet**

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

12 Jun 2025

12 Jun 2026

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners Tech IOSH MIFSM MFPA

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

#### The Scheme

Scheme Name Maple Croft

Scheme Address 2-10 Maple Croft Block 2-10, Leeds

Postcode LS17 6AN

Region Yorkshire

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance None

Number of on-site Accent staff Scheme Manager Part-Time

Number of other (non-Accent) staff

Contract Cleaners in common areas

### The Building

Accommodation Type Leasehold for Older People (S60)

Build Date Jan 1 1920

Number Of Homes 5

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Cement Render, Facing Brick

Roof construction Timber

Roof covering Flat Roof, Plain Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Conversion

Number of storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?) 1 protected

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Asset ID: 30982 2-10 Maple Croft Block 2-10, Leeds Fire Detection and Warning System Flats and common areas not linked Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection **Emergency Lighting Provision** Non Maintained System - Common Areas Portable Fire Extinguishers supplied/fitted Yes Fixed Fire Fighting Installations No **Customers** 10 Number of occupants Leasehold, Leasehold for Older People Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 1 0 Overdue Annual Emergency Lighting tests 0 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors Dwelling Fire doors due for replacement within 5 years 0

# **Fire Risk Assessment Survey Results**

### **Scheme and Building Information**

Photo



12/06/2025

12

Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment Annual Re-Assessment

Type of Risk Assessment Type 1 (Common Parts Only - Non Destructive)

Quantity

Fire & Safety Assessor Steven Manners Tech IOSH MIFSM MFPA

Enforcing Fire Authority West Yorkshire

Scheme Tel. No

Other staff in attendance None

Number of on-site Accent staff Scheme Manager Part-Time

Number of other (non-Accent) staff

Contract Cleaners in common areas

Scheme Inspection completed Yes

Number of occupants 10

Personal Emergency Evacuation Plans in place N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Conversion

Number of Storeys 2

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected) 1 protected

Number of external staircases None

External balcony part of escape route?

Unusual features None

### Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats and common areas not linked

Grade of Fire Alarm Grade D

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted Yes

Water Extinguisher(s) present

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present

Yes

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no

obvious damage?

Comment All in good condition at the time of inspection.

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment All records are held on ActiveH. Last test date : -

27/09/2021

Generated 13/06/2025 16:01:43

Yes

Electrical App/PA Testing - tested within past 12 months? Yes

Comment Tested 07/2025 labels on electrical equipment.

Absence of trailing leads and adapters?

Comment None found at the time of inspection.

Evidence that mobility scooters are not being stored/charged in N/A

common areas?

Comment None on Scheme.

Is there a purpose built mobility scooter store/charging area?

MIS-AMS ActiveH - Fire Risk Assessment Report Page 5 of 14

2-10 Maple Croft Block 2-10, Leeds Asset ID: 30982

Not required. Comment

Does the building have a lightning protection system? No

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme? No

No Gas on Scheme. Comment

Other Sources of Ignition

Yes Is there a no smoking policy in place, which is enforced and adhered

to?

Comment Moking is not allowed within the communal areas,

residents are allowed to smke within their flats.

Yes

Adequate security against arson?

Comment Fronmt and back doors were secured at the time of

inspection. Ther is CCTV throughout the building.

Yes Are refuse/recycling bin areas managed and suitably located?

Comment Ther is an area at the rear of the building where bins

are stored.

Are there communal cooking facilities at this scheme? No

Comment

Housekeeping

N/A Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?

Comment All electrical consumer units are within residents

flats.

Yes Are unnecessary accumulations of combustible materials or waste avoided?

Comment Some artificial flowers were found in the corridors,

The Housing Partner has been made aware and will deal.

Yes Are combustible materials and substances separated from ignition

Nothing Found at the time of inspection. Comment

N/A

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment Furniture is not allowed within the communal areas.

sources and stored appropriately?

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment Nothing F

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Escape routes unobstructed and safe to use?

Exits immediately openable without a key and/or failsafe's function

correctly? Comment

Comment

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Comment

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Yes

Nothing Found at the time of inspection.

Yes

There is a aingle direction of travel from the first floor to a protected staircase. The ground floor flats have

alternative means of escape.

Yes

The escape routes were not obstructed although some items were found within the corridors. See

observations.

Yes

THumb turns are provided on front and rear doors.

Yes

All travel distances are within the guidelines

Yes

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire

spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment

As far as can be reasonably ascertained, is the compartmentation

within roof spaces of a satisfactory standard?

Comment

Loft hatches fire resisting?

Comment

Yes

Some compartmentatin work is being carried out within the roof space.

Yes

Pictures that are hung on the wall are behind glass and fastened with brackets and screws.

N/A

None Fitted.

Yes

See above.

Yes

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory

standard? Comment

Comment

Comment

Do external walls, doors, windows and anything attached to the

exterior, limit fire spread?

If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available?

Are roller shutter doors that are required to be FR, fire resisting and

self-closing?

Comment

N/A

No Cross corridors on the scheme.

Yes

Traditional construction with Tudor style rendering.

N/A

None Fittted.

N/A

None Fitted.

**Emergency Escape Lighting** 

Is the emergency lighting correctly specified and installed as per

current standards?

Comment

Comment

Emergency lighting units in good condition and securely fixed to

walls/ceilings?

Records of monthly/annual testing available?

Comment

Yes

Yes

All in good condition at the time of inspection.

Yes

Tested by the SHP Monthly and Tunstall Annually.

Last Monthly Test : - 08/05/2025 Last Annual Test : - 20/10/2024

**Fire Safety Signs and Notices** 

Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Directional fire escape signage in place and adequate?

Comment

Comment

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

Do common area fire doors display the correct signage on both sides

where applicable?

Comment

Yes

See observations.

Yes

N/A

None fitted.

Yes

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 8 of 14

Generated 13/06/2025 16:01:43

Comment Detection in all the communal areas.

Yes

Yes

Yes

N/A

N/A

N/A

Last Annual Test : - 11/04/2025

Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Comment

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Comment Tested by Tunstall Annually.

Fire alarm components in good condition and securely fixed to

walls/ceilings?

Comment All in good condition at the time of inspetion.

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Comment none fitted.

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Comment None of the above

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

Comment No fire Panel

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations

Yes

provided at this scheme?

Comment only provided within the scheme office, residents are

not trained to use them.

Portable fire extinguishers - appropriate type/number/position? Yes

Comment

Correct signage displayed by each fire extinguisher?

Comment

Fire blanket in communal kitchen, secured to the wall, complete with N/A

signage?

Comment None fitted.

Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to N/A

outlet valves?

Comment none fitted.

Records available of fire fighting equipment servicing within past 12

months?

1110111113:

Comment Records available on ActiveH and label visible on

extinguisher.

**Management of Fire Safety** 

# Asset ID: 30982 2-10 Maple Croft Block 2-10, Leeds No Are these premises regulated by the Building Safety Regulator under the Building Safety Act? Comment No Are there other Responsible Persons who share or have fire safety duties in respect of the premises? How will this sharing be achieved? Is an office or IL scheme being inspected? Yes Comment ILS. N/A IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens? Comment Not required N/A Offices - Are there suitable arrangements for ensuring the premises are evacuated? Comment N/A Offices - Are there suitable arrangements for evacuating disabled Comment Offices - Suitable arrangements for meeting the fire service on arrival N/A and proving relevant information? Comment Offices/IL Schemes - Is there a suitable assembly point? Yes Rear Carpark. Comment N/A Offices - Are fire drills carried out at appropriate intervals? Comment **Passenger Lift** Is the scheme fitted with a passenger lift? No Comment **Premises Inspection Box** No Is there a premises information box for fire & rescue service use? Comment **Evacuation Policy** Are there suitable arrangements for summoning the fire service? Yes Comment Action notices are throughout the building. Residents are instructed to diall 999 and ask for the fire service.

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?

Comment

Yes

### **Engagement with Residents**

Has information of fire procedures been disseminated to residents?

Comment

Is general fire safety information disseminated to residents?

Comment

Yes

Residents have been given a leaflet with the evacuation procedure for their building, A leaflet describing the importance of the flat entrance door being in good condition, instructions to report any defect are also given to each resident.

All information is available on the website and included in a new residents induction pack.

Yes

Residents have been given a leaflet with the evacuation procedure for their building, A leaflet describing the importance of the flat entrance door being in good condition, instructions to report any defect are also given to each resident.

All information is available on the website and included in a new residents induction pack.

### FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Comment

Yes

### **Miscellaneous**

Are there any other observations/actions to raise that are not covered above.

Are there fire related remedial works required at this property, that will affect the fabric of the building?

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

Some fire doors did not fully close so works orders have been raised with our contractors.

Some minor works were required which have been raised with our contractors.

Unauthorised items were found in communal areas and arrangements were made for their removal.

Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.

A number of fire doors were found to be wedged or propped open. Fire doors are there to keep you safe and me kept shut at all times.

No

No

Yes

No

No

Yes

No

No

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 11 of 14

Generated 13/06/2025 16:01:43

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.		·		, J	
	•	evention measures t the hazard from th		he time of this risk bability of ignition) a	at this
LOW	X	MEDIUM		нідн	
any procedural	arrangements ob	•	of the assessr	he fire protection aff ment, it is considere	
MINOR		MAJOR	X	CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).	
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.	
CRITICAL	There is significant potential for serious injury or death of one or more occupants.	

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

ne Overall Risk Level for this asset is:	Trivial
ne Overali Risk Level for this asset is:	