# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 33500 Beechwood Court Back Beachwood Grove, Leeds

#### **Cover Sheet**

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

15 Apr 2025

15 Apr 2028

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners Trch IOSH MIFSM MFPA

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

#### The Scheme

Scheme Name Beechwood Court

Scheme Address Beechwood Court Back Beachwood Grove, Leeds

Postcode LS4 2HS

Region Yorkshire

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance

None

Number of on-site Accent staff

None

Number of other (non-Accent) staff

None

## The Building

Accommodation Type Market Rent (S77)

Build Date Jan 1 1987

Number Of Homes 6

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Facing Brick, UPVC Cladding

Roof construction Timber

Roof covering Interlocking Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

1 protected in each block

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

**Beechwood Court Back Beachwood Grove, Leeds** Asset ID: 33500 Flats only Fire Detection and Warning System Grade D Grade of fire alarm Category of fire alarm LD2 Additional Protection Non Maintained System - Common Areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 20 Number of occupants General Needs, Market Rent Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests Overdue Annual Emergency Lighting tests 0 0 Overdue Weekly Fire Alarm Testing Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors Dwelling Fire doors due for replacement within 5 years 0

# **Fire Risk Assessment Survey Results**

## **Scheme and Building Information**

Photo



Date of Fire Risk Assessment 15/04/2025

FRA Frequency (Months) 36

Purpose of Fire Risk Assessment 3 year Re-Assessment

Type of Risk Assessment Type 1 (Common Parts Only - Non Destructive)

Quantity

Fire & Safety Assessor Steven Manners Trch IOSH MIFSM MFPA

Enforcing Fire Authority West Yorkshire

Scheme Tel. No

Other staff in attendance None

Number of on-site Accent staff

None

Number of other (non-Accent) staff

None

Scheme Inspection completed Yes

Number of occupants 20

Personal Emergency Evacuation Plans in place N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of Storeys 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

1 protected in each block

Number of external staircases None

External balcony part of escape route?

Unusual features None

# Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Mixed

Fire Detection and Warning System Flats only

Grade of Fire Alarm Grade D

Category of Fire Alarm LD2 Additional Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present No

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no

obvious damage?

Comment All in good condition at the time of inspection.

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Communal area certificate date 22/01/2021

Residential flats checked at various times dependant on access. dates can be found on

ActiveH.

Yes

Yes

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment Not required.

Absence of trailing leads and adapters?

Comment

Evidence that mobility scooters are not being stored/charged in Yes

common areas?

**Beechwood Court Back Beachwood Grove, Leeds** Asset ID: 33500

Comment None at the schemeat the time of inspection.

Is there a purpose built mobility scooter store/charging area? N/A

Comment Not required.

No Does the building have a lightning protection system?

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered

to?

Comment Smoking is not allowed within the communal area of

the building but residents are allowed to smoke

within their flats.

No

Yes

Adequate security against arson? Yes

Comment Thre is a fob entry system to the main entrance.

Are refuse/recycling bin areas managed and suitably located? Yes

Stored away from the building. Comment

No Are there communal cooking facilities at this scheme?

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general

waste, contractors waste and and residents personal items?

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment

Comment None found at the time of inspection.

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Comment

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

Comment No furniture allowed within the communal area and none was found at the time of inspection.

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 6 of 13

Generated 16/04/2025 16:03:16

Yes

Individual cupboards are built into the wall. no items found within the cupboards at the time of inspection.

Yes

Yes

none found at the time of inspection.

N/A

**Beechwood Court Back Beachwood Grove, Leeds** Asset ID: 33500

**Other Significant Fire Hazards** 

Are all other significant fire hazards adequately controlled?

None found at the time of inspection.

N/A

Yes

Yes

Yes

Yes

Yes

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Comment Ther is one protected staircase within the building, the stairs are protected by a lobby on each level.

Yes Escape routes unobstructed and safe to use?

All clear at the time of inspection. Comment

Yes Exits immediately openable without a key and/or failsafe's function

correctly? Comment

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Comment Travel distances are within the guidelines.

Escape routes lead to final exits and open in direction of escape where

necessary? Comment


Observation

**Priority** Referred To Required By: Task ID

Internal - Low

Pictures need screwing g to wall or removing HP informed and dealing.





## Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire

spread (walls, floors, ceilings)?

All walls are painted brick. Comment

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 7 of 13

Generated 16/04/2025 16:03:16

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment None fitted.

As far as can be reasonably ascertained, is the compartmentation

within roof spaces of a satisfactory standard?

Comment no access to the roof space from the communal

N/A

N/A

N/A

Yes

Yes

Loft hatches fire resisting? A/A

Comment None Fitted.

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Comment No cross corridor doors at this scheme.

Do external walls, doors, windows and anything attached to the

exterior, limit fire spread?

Comment

below each balcony that would promote fire spread.

If Smoke Control Systems (AOV's) are fitted, are the records of annual.

N/A

If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?

Comment None fitted.

Are roller shutter doors that are required to be FR, fire resisting and N/A

self-closing?

Comment None fitted

Observation Priority Referred To Required By: Task ID

balcony of wood construction with metal frame znd glass frontage





There is a steel framed balcony with a timber floor fronted by toughened glass. There is no fire loading

## **Emergency Escape Lighting**

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Emergency lighting units in good condition and securely fixed to Yes

walls/ceilings?

Comment All in good condition at the time of inspection.

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 8 of 13

Generated 16/04/2025 16:03:16

Records of monthly/annual testing available?

Yes

Comment

Tests are carried out by our contractors Tunstall.

Last test dates ; -Annual 21/10/2024 Monthly 07/04/2025

Observation Priority Referred To Required By: Task ID

non maintained emergency lighting





## **Fire Safety Signs and Notices**

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?

Comment

Directional fire escape signage in place and adequate?

Comment

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

Do common area fire doors display the correct signage on both sides

where applicable?

Comment

Yes

Notices are displayed throughout the building.

Yes

See observations.

N/A

No Lift.

Yes

Observation Priority Referred To Required By: Task ID

Directional signage and evacuation notices





## Means of giving Warning in case of Fire

Asset ID: 33500 Beechwood Court Back Beachwood Gro	ove, Leeds
Is the scheme fitted with a communal area fire alarm?	No
Comment	
Fire Extinguishing Equipment	
Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?	No
Comment	
Management of Fire Safety	
Are these premises regulated by the Building Safety Regulator under	No
the Building Safety Act? Comment	
Are there other Responsible Persons who share or have fire safety duties in respect of the premises?	No
How will this sharing be achieved?	
Is an office or IL scheme being inspected?	No
Comment	
Passenger Lift	
Is the scheme fitted with a passenger lift?	No
Comment	
Premises Inspection Box	
Is there a premises information box for fire & rescue service use?	No
Comment	
Evacuation Policy	
Are there suitable arrangements for summoning the fire service?	Yes
Comment	Reesidents are advised to call the fire service by dialing 999
Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?	Yes

# **Engagement with Residents**

Comment

Has information of fire procedures been disseminated to residents?

res

Comment

All residents received a letter containing leaflets which gave Fire safety advice including the evacuation proceedure for their building and advice on flat doors. Information is also available on the

website.

Is general fire safety information disseminated to residents?

Yes

Comment

All residents received a letter containing leaflets which gave Fire safety advice including the evacuation proceedure for their building and advice on flat doors. Information is also available on the website.

## **FRA Frequency**

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Comment

Yes

#### **Miscellaneous**

Are there any other observations/actions to raise that are not covered

above.

Are there fire related remedial works required at this property, that will affect the fabric of the building?

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

No

No

No

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

0	•		ved at the time of this risk (the probability of ignition) at this
LOW	X	MEDIUM	нідн
any procedural	arrangements ob	- ·	pants, the fire protection afforded and assessment, it is considered that the e:

MINOR MAJOR X CRITICAL

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

ne Overall Risk Level for this asset is:	Trivial
ne Overali Risk Level for this asset is:	