Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 5966 St Phillips Court, Bradford

Cover Sheet

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

13 Oct 2023

13 Oct 2026

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Steven Manners

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name St Philips Court

Scheme Address St Phillips Court, Bradford

Postcode BD8 9PD

Region Yorkshire

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority West Yorkshire

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type General Needs (S30)

Build Date Jan 1 1983

Number Of Homes 18

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Facing Brick

Roof construction Timber

Roof covering Interlocking Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

One protected

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Asset ID: 5966 St Phillips Court, Bradford			
Fire Detection and Warning System	Flats only		
Grade of fire alarm	Grade D		
Category of fire alarm	LD3 Minimum Protection		
Emergency Lighting Provision	Maintained system - Common areas		
Portable Fire Extinguishers supplied/fitted	No		
Fixed Fire Fighting Installations	No		
Customers			
Number of occupants	30		
Occupant tenure type breakdown	General Needs, Supported Housing		
Fire Safety Related Customer Safety Servicing			
Overdue communal gas safety checks	0		
Overdue domestic gas safety checks	0		
Overdue communal electrical condition checks	0		
Overdue domestic electrical condition checks	0		
Overdue alarm call pull chord tests	0		
Overdue communal PAT testing	0		
Overdue customer mobility scooter PAT testing	0		
Overdue Monthly Emergency Lighting Switch Tests	3		
Overdue Annual Emergency Lighting tests	3		
Overdue Weekly Fire Alarm Testing	0		
Overdue Fire Panel - Six Monthly Testing			
Overdue Fire Safety Equipment tests			
Building Fire Safety Surveys - Communal Doors			
Failing Communal Fire Doors	0		
Communal Fire doors due for replacement within 5 years	0		
Dwelling Doors			
Failing Dwelling Fire Doors	0		
Dwelling Fire doors due for replacement within 5 years	0		

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment 13/10/2023

FRA Frequency (Months) 36

Purpose of Fire Risk Assessment 3 year Re-Assessment

Type of Risk Assessment

Type 1 (Common Parts Only - Non Destructive)

Quantity

Fire & Safety Assessor Steven Manners

Enforcing Fire Authority West Yorkshire

Scheme Tel. No

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

Contract Cleaners in common areas

Scheme Inspection completed Yes

Number of occupants 30

Personal Emergency Evacuation Plans in place N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of Storeys 2

Number of floors on which car parking is provided 0

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

One protected

Number of external staircases

None

External balcony part of escape route?

Unusual features None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats only

Grade of Fire Alarm Grade D

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Maintained system - Common areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present No

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present No

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment All in good condition at the time of inspection

Valid Electrical Installation Condition Reports held on file? (Common Yes

Areas & General Needs Flats)

Comment All records are available on ActiveH

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment Not required

Absence of trailing leads and adapters? Yes

Comment None found

Evidence that mobility scooters are not being stored/charged in Yes

common areas?

Comment None on scheme

Is there a purpose built mobility scooter store/charging area?

Comment Not required

Does the building have a lightning protection system?

Comment

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment All records are available on ActiveH

Valid LGSR held on file for fixed communal area gas appliances? Yes

(Boilers)

Comment All records are available on ActiveH

Valid LGSR held on file for residential flats that contains gas

appliances?

Comment All records are available on ActiveH

Are smoke/heat detectors within General Needs flats subject to an

annual inspection and the results

Comment Residents are responsible to test smoke detectors, they are tested with the CO Detectors annually

Yes

Yes

No

No

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered Yes

to?

Comment No smoking allowed in the communal areas but

smoking is allowed in residents flats

Adequate security against arson? Yes

Comment Buzz in system to property

Are refuse/recycling bin areas managed and suitably located?

Yes

Comment B8ns stored away from the building

Are there communal cooking facilities at this scheme?

Comment

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?

Comment Electrical cupboard leading to flats 7 and 8 have

combustible items stored

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment As above

St Phillips Court, Bradford Asset ID: 5966

Are combustible materials and substances separated from ignition

sources and stored appropriately?

As above Comment

Furniture/furnishings in good condition, fire retardant/resistant and

comply with modern standards and regulations?

No furniture allowed in the communal areas Comment

Observation **Priority** Referred To Required By: Task ID

Internal - Medium

No

N/A

Yes

Yes

Yes

Combustible items stored in electrical cupboard block 1 To 6 children's toys on escape route





Housing Partner

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled? Yes

Comment None found at the time of inspection

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Comment

No Escape routes unobstructed and safe to use?

Comment Some items were found in the communal corridor at

the time of inspection. Housing Partner informed

Exits immediately openable without a key and/or failsafe's function

correctly? Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

All travel distances are within the guidelines Comment

Yes

Escape routes lead to final exits and open in direction of escape where necessary?

Comment

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment All in good condition at the time of inspection

Yes

Yes

No

Yes

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment Brick walls on escape route,

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Comment Not required

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Comment All in good condition at the time of inspection

Loft hatches fire resisting?

Comment

As far as can be reasonably ascertained, is the fire stopping above
cross corridor fire doors within suspended ceiling void of a satisfactory

standard?

Comment

Fire stopping abo e Communal lobb

Comment Fire stopping abo e Communal lobby doors was in good condition at the time of inspection

Do external walls, doors, windows and anything attached to the Yes

o external waits, doors, windows and anything attached to the

exterior, limit fire spread?

Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual N/A

Comment None fitted

Are roller shutter doors that are required to be FR, fire resisting and N/A

Are roller shutter doors that are required to be FR, fire resisting and self-closing?

Comment None fitted

Observation Priority Referred To Required By: Task ID

Communal Fire door leading to flats 9 and 10 requires repairing. Hinges need replacing and door adjusting to fit to rebate Order No. 1122777

testing available?







St Phillips Court, Bradford Asset ID: 5966

Observation **Priority** Referred To Required By: Task ID

Electric cupboard door in block 7 to 12 requires adjusting to allow door to close to rebate code C2014 Order No 1122781

Repair - Non **Emergency**

Building Safety Manager



Observation **Priority** Referred To Required By: Task ID

Communal door leading to flats 1 and 2 requires adjusting to close to rebate. Renew smoke seal and hinges Order Number 1122784

Repair - Non **Emergency**

Building Safety Manager





Yes

Yes

Yes

Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Comment

Emergency lighting units in good condition and securely fixed to

walls/ceilings?

Yes

Records of monthly/annual testing available?

All records are available on ActiveH Comment

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Signage displayed throughout the building Comment

Yes Directional fire escape signage in place and adequate?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 9 of 14

Generated 13/10/2023 16:04:55

All in good condition at the time of inspection

Is there suitable LIFT signage i.e. do not use in case of fire?

Do common area fire doors display the correct signage on both sides

where applicable?

Comment

Comment

Comment

Signage displayed throughout the building

N/A

No lift at this scheme

Yes

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Comment

Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?

Comment

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Comment

Fire alarm components in good condition and securely fixed to

walls/ceilings?

Comment

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Comment

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?
Comment

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

Comment

Yes

Smoke detection within the communal area

Yes

Yes

Tunstall complete weekly tests and record them

Yes

All in good condition at the time of inspection

N/A

None fitted

N/A

None present

No

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations

provided at this scheme?

Comment

No

Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?

Comment

Will this FRA be shared will all Accountable Persons for the premises?

Yes

Yes

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 10 of 14

Generated 13/10/2023 16:04:55

Comment Available on ActiveH

How will this sharing be achieved?

As above

Are there other Responsible Persons who share or have fire safety

duties in respect of the premises? How will this sharing be achieved?

Is an office or IL scheme being inspected?

Comment

Passenger Lift

Is the scheme fitted with a passenger lift?

Comment

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

Comment

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Comment All residents are instructed to contact the fire

service by dialing 999

Taking FRA findings, is the evacuation policy appropriate for the

scheme as per latest guidance?

Comment

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Yes

Comment On induction and by signage throughout the

building, website and leaflets

Is general fire safety information disseminated to residents?

Comment As above

FRA Frequency

Taking the findings of this assessment into account, is the frequency of

the FRA correct?

Comment

Yes

Yes

Yes

No

doors are there to keep you safe and me kept shut at all times.

Miscellaneous

Are there any other observations/actions to raise that are not covered above.	Yes
Action leading to a repair	Yes
Internal administrative Action	Yes
Are there fire related remedial works required at this property, that will affect the fabric of the building? Comment	No
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	Yes
Some fire doors did not fully close so works orders have been raised with our contractors.	Yes
Some minor works were required which have been raised with our contractors.	Yes
Unauthorised items were found in communal areas and arrangements were made for their removal.	Yes
Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.	No
A number of fire doors were found to be wedged or propped open. Fire	No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.					
1	•	evention measures ob t the hazard from the			at this
LOW	X	MEDIUM		HIGH	
any procedural	arrangements ob	e of the building, the observed at the time of the event of a fire would	the assessme	-	
MINOR		MAJOR		CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	