

This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 8903 Victoria Court Victoria Road, Huddersfield

Cover Sheet

Photo

Date of Fire Risk Assessment Date of Next Fire Risk Assessment FRA Frequency (Months) Purpose of Fire Risk Assessment Type of Fire Risk Assessment Fire & Safety Assessor



06 May 2025 06 May 2026 12 Annual Re-Assessment Type 1 (Common Parts Only - Non Destructive) Steven Manners Tech IOSH Mifsm MFPA

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

Victoria Court Victoria Road, Huddersfield

The Scheme

Scheme Name	Lockwood Road
Scheme Address	Victoria Court Victoria Road, Huddersfield
Postcode	HD1 3TF
Region	Yorkshire
Scheme Manager	
Scheme Tel. No	
Scheme Inspection Completed	Yes
Enforcing Fire Authority	West Yorkshire
Other staff in attendance	Cherries Ackie
Number of on-site Accent staff	Scheme Manager Part-Time
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	CAT2 Housing for Older People (S28)
Build Date	Jan 1 1987
Number Of Homes	32
Homes breakdown	Flat
External wall construction	Natural Stone
External wall finish	Artificial/Natural Stone
Roof construction	Timber
Roof covering	Plain Pitched
PEEPs in place where necessary	Yes
Current Evacuation Strategy	Stay Put (Delayed) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	2
Number of floors on which car parking is provided	0
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	3 protected
Number of External Staircases	None
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Fire Detection and Warning System	Flats and common areas not linked
Grade of fire alarm	Grade A
Category of fire alarm	LD2 Additional Protection
Emergency Lighting Provision	Mixed system - Common areas
Portable Fire Extinguishers supplied/fitted	Yes
Fixed Fire Fighting Installations	No

Customers

Number of occupants	45
Occupant tenure type breakdown	CAT2 Housing for Older People, General Needs,
	Sheltered Schemes

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0	
Overdue domestic gas safety checks	0	
Overdue communal electrical condition checks	0	
Overdue domestic electrical condition checks	0	
Overdue alarm call pull chord tests	0	
Overdue communal PAT testing	0	
Overdue customer mobility scooter PAT testing	0	
Overdue Monthly Emergency Lighting Switch Tests	1	
Overdue Annual Emergency Lighting tests	1	
Overdue Weekly Fire Alarm Testing	1	
Overdue Fire Panel - Six Monthly Testing	1	
Overdue Fire Safety Equipment tests	1	
Building Fire Safety Surveys - Communal Doors		
Failing Communal Fire Deere	0	

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo

Date of Fire Risk Assessment
FRA Frequency (Months)
Purpose of Fire Risk Assessment
Type of Risk Assessment
Quantity
Fire & Safety Assessor
Enforcing Fire Authority
Scheme Tel. No
Other staff in attendance
Number of on-site Accent staff
Number of other (non-Accent) staff
Scheme Inspection completed
Number of occupants
Personal Emergency Evacuation Plans in place
Current Evacuation Strategy
Conversion or purpose-built
Number of Storeys
Number of floors on which car parking is provided
Is there a habitable basement?
No. of internal staircases (protected/unprotected)
Number of external staircases
External balcony part of escape route?
Unusual features



06/05/2025
12
Annual Re-Assessment
Type 1 (Common Parts Only - Non Destructive)
1
Steven Manners Tech IOSH Mifsm MFPA
West Yorkshire
Cherries Ackie
Scheme Manager Part-Time
Contract Cleaners in common areas
Yes
45
Yes
Stay Put (Delayed) Evacuation
Purpose Built
2
0
No
3 protected
None
No

None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Mixed
Fire Detection and Warning System	Flats and common areas not linked
Grade of Fire Alarm	Grade A
Category of Fire Alarm	LD2 Additional Protection
Emergency Lighting Provision	Mixed system - Common areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	Yes
Water Extinguisher(s) present	No
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	Yes
Fire Blanket(s) present	Yes
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

Electrical Sources of Ignition

Electrical installation within common areas in good condo obvious damage?	dition and no	Yes
Comment		All electrical equipment is in good condition at the time of inspection.
Valid Electrical Installation Condition Reports held on fil Areas & General Needs Flats)	e? (Common	Yes
Comment		All test records are available on ActiveH.Last test date 22/02/2021
Electrical App/PA Testing - tested within past 12 months	?	Yes
Comment		All test records are available on ActiveH . Last test date 11/07/2024
Absence of trailing leads and adapters?		Yes
Comment		None found at the time of inspection.
Evidence that mobility scooters are not being stored/ch common areas?	arged in	Yes
Comment		None found at the time of inspection.
MIS-AMS ActiveH - Fire Risk Assessment Report	Page 5 of 17	Generated 06/05/2025 16:01:40

Is there a purpose built mobility scooter store/charging area?	N/A
Comment	Not r
Does the building have a lightning protection system?	No
Comment	

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Comment

Valid LGSR held on file for fixed communal area gas appliances? (Boilers) Comment

Valid LGSR held on file for residential flats that contains gas appliances?

Comment

Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results Comment

Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to? Comment

Adequate security against arson?

Comment

Are refuse/recycling bin areas managed and suitably located?

Comment

Are there communal cooking facilities at this scheme?

Comment

Are reasonable measures taken to prevent fires as a result of cooking? Comment Not required. No

Central heating system for the whole scheme is controled by boilers in a central location within the building.

Yes

Yes

All records are available on ActiveH . Last test date 23/02/2025

N/A

No gas instalations within the residents flats.

Yes

Tunstall test the detection annualy, all records are available on ActiveH.

Yes

Smoking is not allowed within the communal areas of the building. Residents are allowed to smoke within their flats.

Yes

THere is a fob / intercomme system at the main entrance. All other doors to the scheme are secured ant there is cctv throughout.

Yes

Yes

There is a small Kitchen adjacent to the communal lounge. this is mainly used for making tea and coffee.

Yes

There is a small Kitchen adjacent to the communal lounge. this is mainly used for making tea and coffee

Where there is extraction in communal kitchens, are filters and ductwork changed/cleaned regularly?	N/A
Comment	None fitted.

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items? Comment	
Are unnecessary accumulations of combustible materials or waste avoided? Comment	
Are combustible materials and substances separated from ignition sources and stored appropriately? Comment	
Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations? Comment	

Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?	Yes
Comment	Nothing found at the time of inspection.

Yes

Yes

Yes

Yes

communal areas.

All secure at the time of inspection.

Nothing found at the time of inspection.

None found at the time of inspection.

All furniture within the communal lounge conforms to the regulations. Furniture is not allowed in other

Means of Escape from Fire

Yes
There are several exits throughout the scheme
Yes
All clear at the time of inspection.
Yes
All exits are push bar to open.
Yes
Alltravel distances are within the guidelines.
Yes

Victoria Court Victoria Road, Huddersfield

Observation	Priority	Referred To	Required By:	Task ID
assembley point.				



Observation	Priority	Referred To	Required By:	Task ID
Television cable obstructing means of escape at rear of building adjacent to the communal kitchen. Requires fixing above door. Emergency order raised. WO	Repair - Emergency	Project Manager (Building Safety)		





Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)? Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products? Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard? Comment

Loft hatches fire resisting?

Comment

Yes

All of a reasonable standard at the time of inspection.

Yes

Nothing on the walls or floor that would promote fire spread at the time of inspection. Yes

Fire damper in bin refuse area

N/A

Work is being carried out by Fire alarm installers, a further inspection will be required on completion of work.

Yes

As far as can be reasonably ascertained, is the fire stopping at cross corridor fire doors within suspended ceiling void of a satis standard?		Yes ry			
Comment		All satisfactory at the tim	e of inspection.		
Do external walls, doors, windows and anything attached to the exterior, limit fire spread?	e	Yes			
Comment		Buiding is of a traditional	construction.		
If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?		N/A			
Comment		None fitted.			
Are roller shutter doors that are required to be FR, fire resisting self-closing?	g and	N/A			
Comment		None fitted.			
Observation	Priority	Referred To	Required By:	Task ID	
Drop down strip required for flat 1 excesive gap at foot of door WO 1279064	Repair - Non Emergency	Project Manager (Building Safety)	31/07/2025	1969738	



loft hatch.



Victoria Court Victoria Road, Huddersfield

Observation	Priority	Referred To	Required By:	Task ID

Notice board



Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards? Comment	Yes
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	All in good condition at the time of inspection.
Records of monthly/annual testing available?	Yes
Comment	All records are available on ActiveH. Last test dates. Monthly : - 06/05/2025 Annual : - 30/04/2025
Fire Safety Signs and Notices	
Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes

locations within the common areas? Comment Directional fire escape signage in place and adequate? Comment Is there suitable LIFT signage i.e. do not use in case of fire? Comment

Do common area fire doors display the correct signage on both sides where applicable?

Comment

MIS-AMS ActiveH - Fire Risk Assessment Report

Signage is visible throughout the building.

Yes

Yes

Yes

Asset ID: 8903 Victor

Victoria Court Victoria Road, Huddersfield

Observation	Priority	Referred To	Required By:	Task ID

Action plan and directional signage



Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Comment

Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?

Comment

Is the fire detection and warning system maintained/tested and all certificates saved on file?

Comment

Fire alarm components in good condition and securely fixed to walls/ceilings?

Comment

Hold open devices operate at the sounding of the alarm and are in a serviceable condition?

Comment

Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?

Comment

Is the fire alarm panel remotely monitored, and if so are there records of regular testing?

Comment

Yes

A new system is being installed at the time of inspection.

Yes

Yes

All records are available on ActiveH.

Yes

A new system is being installed at the time of inspection. Yes

165

All in good working order at the time of inspection.

Yes

Yes

All test records are available on ActiveH. Last test dates. 6 monthly 23/04/2025 Weekly 02/05/2025

Observation	Priority	Referred To	Required By:	Task ID
Fire alarm panel and zone plan				

anel and zone plan



Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installati provided at this scheme?	ons	Yes		
Comment		In high risk areas only.		
Portable fire extinguishers - appropriate type/number/position?		Yes		
Comment				
Correct signage displayed by each fire extinguisher?		Yes		
Comment				
Fire blanket in communal kitchen, secured to the wall, complete signage?	with	Yes		
Comment				
Dry risers - Inlet/outlet boxes secured and/or securing straps fitt outlet valves?	ed to	N/A		
Comment		None fitted.		
Records available of fire fighting equipment servicing within pas months?	t 12	Yes		
Comment		Records available on Active extinguishers.	eH and labeling on	
Observation	Priority	Referred To	Required By:	Task ID

Co2 in laundry, fire blanket in kitchen





Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?	Νο
Comment	
Are there other Responsible Persons who share or have fire safety duties in respect of the premises?	No
How will this sharing be achieved?	
Is an office or IL scheme being inspected?	Yes
Comment	ILS
IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens?	N/A
Comment	Fire wardens not required, the Scheme manager is trained of actions in the event of Fire.
Offices - Are there suitable arrangements for ensuring the premises are evacuated? Comment	N/A
Offices - Are there suitable arrangements for evacuating disabled people? Comment	N/A
Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information? Comment	N/A
Offices/IL Schemes - Is there a suitable assembly point?	Yes
Comment	THere is an assembley point in the car park for those who wish to evacuate.
Offices - Are fire drills carried out at appropriate intervals?	N/A
Comment	No drills required.
Passenger Lift	
Is the scheme fitted with a passenger lift?	Yes
Comment	
Is the lift in full working order at the time of the FRA?	Yes
Comment	All ion good working order at the time of inspection.
Is the lift fitted with a firefighters switch?	No
Comment	
Servicing and insurance inspection - Evidence of regular	Yes
servicing/maintenance?	
servicing/maintenance? Comment	Last test date 18/02/2025. Records are available on ActiveH.

Asset ID: 8903 Victoria Court Victoria

1 1

Victoria Court Victoria Roa	ad, Huddersfield
-----------------------------	------------------

Observation		 Priority	Referred To	Required By:	Task ID
lift signage					
	Case of fire				
	do not use lift				

Premises Inspection Box

Is there a premises information box for fire & rescue service use?

Comment

Evacuation Policy

Are there suitable arrangements for summoning the fire service?

Comment

Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?

Comment

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Comment

Is general fire safety information disseminated to residents?

Comment

No

Yes

The fire alarm is monitored but residents are also advised to call 999. Yes

Yes

A leaflet explaining the evacuation proceedure for their building has been sent to each resident, they have also had informatiopon about their flat front door and how to report any defects. Information can also be found on the website. an induction package is given to any new resident moving in to a flat. Yes

As Above A leaflet explaining the evacuation proceedure for their building has been sent to each resident, they have also had informatiopon about their flat front door and how to report any defects. Information can also be found on the website. an induction package is given to any new resident moving in to a flat.

FRA Frequency

Taking the findings of this assessment into account, is the frequency of
the FRA correct?Yes

Comment

Miscellaneous

Are there any other observations/actions to raise that are not covered above.	Yes
Action leading to a repair	Yes
Internal administrative Action	No
Are there fire related remedial works required at this property, that will affect the fabric of the building? Comment	No
Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).	Yes
Some fire doors did not fully close so works orders have been raised with our contractors.	No
Some minor works were required which have been raised with our contractors.	Yes
Unauthorised items were found in communal areas and arrangements were made for their removal.	No
Not all records were up to date, as noted in the table below. Arrangements have been made for these to be completed.	No
A number of fire doors were found to be wedged or propped open . Fire doors are there to keep you safe and me kept shut at all times.	No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW	X	MEDIUM	нісн		
-----	---	--------	------	--	--

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR	MAJOR	X	CRITICAL	

The definition of the above terms is as follows: *FRA Review Frequency*

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	intolerable

When the level of risk is established, the action level can be read from the table below:

Victoria Court Victoria Road, Huddersfield

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial