# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 991 30 - 34 St Edmunds Walk, Peterborough

#### **Cover Sheet**

Photo



Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

28 Mar 2025

28 Mar 2028

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Gary Bredin AlFireE

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

#### The Scheme

Scheme Name Concept 36

Scheme Address 30 - 34 St Edmunds Walk, Peterborough

Postcode PE7 8GQ

Region East

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority Cambridgeshire fire and Rescue service

Other staff in attendance None

Number of on-site Accent staff None

Number of other (non-Accent) staff

Contract Cleaners in common areas

### The Building

Accommodation Type

Build Date Jan 1 2007

Number Of Homes 3

Homes breakdown Flat

External wall construction Timber Frame

External wall finish Facing Brick, Paint Render

Roof construction Timber

Roof covering Slate Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

One unprotected

Number of External Staircases None

External Balcony part of escape route?

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

30 - 34 St Edmunds Walk, Peterborough Asset ID: 991 Fire Detection and Warning System Flats only Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection **Emergency Lighting Provision** Non Maintained System - Common Areas Portable Fire Extinguishers supplied/fitted No Fixed Fire Fighting Installations No **Customers** 8 Number of occupants Intermediate, Shared Ownership Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 0 0 Overdue Annual Emergency Lighting tests Overdue Weekly Fire Alarm Testing 0 Overdue Fire Panel - Six Monthly Testing Overdue Fire Safety Equipment tests 1 **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** 0 Failing Dwelling Fire Doors

Dwelling Fire doors due for replacement within 5 years

0

## **Fire Risk Assessment Survey Results**

#### **Scheme and Building Information**

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Type of Risk Assessment

Purpose of Fire Risk Assessment

Quantity

Fire & Safety Assessor

**Enforcing Fire Authority** 

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

**Current Evacuation Strategy** 

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

29/03/2022

36

3 year Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

1

Gary Bredin AlFireE

Cambridgeshire fire and Rescue service

None

None

Contract Cleaners in common areas

Yes

8

N/A

Stay Put (Delayed) Evacuation

Purpose Built

3

0 No

One unprotected

01.10 di...p. 01.0

None

No

None

## Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats only

Grade of Fire Alarm Grade D

Category of Fire Alarm LD3 Minimum Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted No

Water Extinguisher(s) present

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present No

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present

Yes

#### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no

obvious damage?

Comment

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Last test April 2024

Electrical App/PA Testing - tested within past 12 months?

N/A

Comment

Absence of trailing leads and adapters? Yes

Comment

Evidence that mobility scooters are not being stored/charged in Yes

common areas?

Comment

Is there a purpose built mobility scooter store/charging area?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 5 of 12

Generated 25/04/2025 15:00:36

Yes

Yes

Asset ID: 991 30 - 34 St Edmunds Walk, Peterborough	
Comment	
Does the building have a lightning protection system?	No
Comment	
Gas installations	
Is there a commercial/domestic gas supply to the scheme?	No
Comment	
Other Sources of Ignition	
Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	
Adequate security against arson?	Yes
Comment	Electronic entry system in place.
Are refuse/recycling bin areas managed and suitably located?	Yes
Comment	
Are there communal cooking facilities at this scheme?	No
Comment	
Housekeeping	
Are all electrical/intake/service cupboards secure and free from general	Yes
waste, contractors waste and and residents personal items?  Comment	
Are unnecessary accumulations of combustible materials or waste	Yes
avoided?	
Comment	N/A
Are combustible materials and substances separated from ignition sources and stored appropriately?	N/A
Comment	
Furniture/furnishings in good condition, fire retardant/resistant and	N/A
comply with modern standards and regulations?  Comment	
Other Significant Fire Hazards	
Are all other significant fire hazards adequately controlled?	No
Comment	

#### Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?

Comment

Escape routes unobstructed and safe to use?

Comment All areas were clear at the time of the audit

Yes

Yes

Yes

Yes

Exits immediately openable without a key and/or failsafe's function Yes

correctly? Comment

Comment

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Escape routes lead to final exits and open in direction of escape where

necessary?

Observation Priority Referred To Required By: Task ID

All areas were clear at the time of the audit



### Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Comment

Is there reasonable limitation of surface finishes that might promote fire

spread (walls, floors, ceilings)?

Are fire dampers/shutters provided in ducts/refuse chutes to protect N/A

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

means of escape against fire, smoke and combustion products?

within roof spaces of a satisfactory standard?

Comment

This area was not checked during the audit due to lone working at height

Asset ID: 991 30 - 34 St Edmunds Walk, Peterboro	ough
Loft hatches fire resisting?	Yes
Comment	
As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?  Comment	Yes
Do external walls, doors, windows and anything attached to the exterior, limit fire spread?  Comment	Yes
If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?	Yes
Comment	Last test September 2024
Are roller shutter doors that are required to be FR, fire resisting and self-closing?	N/A
Comment	
Emergency Escape Lighting	
Is the emergency lighting correctly specified and installed as per current standards?  Comment	Yes
Emergency lighting units in good condition and securely fixed to walls/ceilings?  Comment	Yes
Records of monthly/annual testing available?	Yes
Comment	Last drop test September 2024
Fire Safety Signs and Notices	
Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes
Comment	
Directional fire escape signage in place and adequate?	Yes
Comment	
Is there suitable LIFT signage i.e. do not use in case of fire?	N/A
Comment	
Do common area fire doors display the correct signage on both sides where applicable?	Yes

# Means of giving Warning in case of Fire

Comment

Asset ID: 991 30 - 34 St Edmunds W	alk, Peterborough
Is the scheme fitted with a communal area fire alarm?	No
Comment	
Fire Extinguishing Equipment	
Is fire extinguishing equipment and/or fixed fire fighting inst provided at this scheme?	allations No
Comment	
Management of Fire Safety	
Are these premises regulated by the Building Safety Regulation the Building Safety Act?  Comment	ator under No
Are there other Responsible Persons who share or have fir duties in respect of the premises?	e safety No
How will this sharing be achieved?	
Is an office or IL scheme being inspected?	No
Comment	
Passenger Lift	
Is the scheme fitted with a passenger lift?	No
Comment	
Premises Inspection Box	
Is there a premises information box for fire & rescue service	e use? No
Comment	
<b>Evacuation Policy</b>	
Are there suitable arrangements for summoning the fire ser	vice? Yes
Comment	It's the responsibility of the customers to summon the emergency services
Taking FRA findings, is the evacuation policy appropriate for	r the Yes

# **Engagement with Residents**

scheme as per latest guidance?

Comment

## 30 - 34 St Edmunds Walk, Peterborough Asset ID: 991 Yes Has information of fire procedures been disseminated to residents? Comment Is general fire safety information disseminated to residents? Yes Comment **FRA Frequency** Yes Taking the findings of this assessment into account, is the frequency of the FRA correct? Comment **Miscellaneous** Are there any other observations/actions to raise that are not covered No above. No Are there fire related remedial works required at this property, that will affect the fabric of the building?

Were there any unsatisfactory aspects of the Fire Risk Assessment?

Comment

(Visible on Building Safety Report).

No

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.					
	•	evention measures o t the hazard from the			at this
LOW	X	MEDIUM		HIGH	
any procedural	arrangements of	e of the building, the observed at the time of the event of a fire wou	the assessi	•	
MINOR		MAJOR		CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>