



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 33965 **Trident House Falcon Court, Stockton on Tees**

Cover Sheet

Photo



Date of Fire Risk Assessment	29 Oct 2025
Date of Next Fire Risk Assessment	29 Oct 2026
FRA Frequency (Months)	12
Purpose of Fire Risk Assessment	Annual Re-Assessment
Type of Fire Risk Assessment	Type 1 (Common Parts Only - Non Destructive)
Fire & Safety Assessor	Kevin Jones GFireE

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name	
Scheme Address	Trident House Falcon Court, Stockton on Tees
Postcode	TS18 3TX
Region	North East
Scheme Manager	Claire Knaggs
Scheme Tel. No	
Scheme Inspection Completed	Yes
Enforcing Fire Authority	Cleveland
Other staff in attendance	None
Number of on-site Accent staff	Scheme Manager Weekdays
Number of other (non-Accent) staff	Contract Cleaners in common areas

The Building

Accommodation Type	Middlesborough Office (L40)
Build Date	Nov 25 2019
Number Of Homes	0
Homes breakdown	
External wall construction	
External wall finish	
Roof construction	
Roof covering	
PEEPs in place where necessary	N/A
Current Evacuation Strategy	Full (Simultaneous) Evacuation
Conversion or purpose-built	Purpose Built
Number of storeys	1
Number of floors on which car parking is provided	1
Is there a habitable basement?	No
Number of internal Staircases (protected or unprotected?)	none
Number of External Staircases	None
External Balcony part of escape route?	No
Unusual features	None
Building Access Conditions for Fire Brigade	Vehicular Access to one or more elevations

Asset ID: 33965 Trident House Falcon Court, Stockton on Tees

Fire Detection and Warning System	Common areas only
Grade of fire alarm	Grade A
Category of fire alarm	LD1 Maximum Protection
Emergency Lighting Provision	Mixed system - Common areas
Portable Fire Extinguishers supplied/fitted	Yes
Fixed Fire Fighting Installations	No

Customers

Number of occupants	10
Occupant tenure type breakdown	

Fire Safety Related Customer Safety Servicing

Overdue communal gas safety checks	0
Overdue domestic gas safety checks	0
Overdue communal electrical condition checks	0
Overdue domestic electrical condition checks	0
Overdue alarm call pull chord tests	0
Overdue communal PAT testing	0
Overdue customer mobility scooter PAT testing	0
Overdue Monthly Emergency Lighting Switch Tests	0
Overdue Annual Emergency Lighting tests	0
Overdue Weekly Fire Alarm Testing	0
Overdue Fire Panel - Six Monthly Testing	
Overdue Fire Safety Equipment tests	1

Building Fire Safety Surveys - Communal Doors

Failing Communal Fire Doors	0
Communal Fire doors due for replacement within 5 years	0

Dwelling Doors

Failing Dwelling Fire Doors	0
Dwelling Fire doors due for replacement within 5 years	0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment	29/10/2025
FRA Frequency (Months)	12
Purpose of Fire Risk Assessment	Annual Re-Assessment
Type of Risk Assessment	Type 1 (Common Parts Only - Non Destructive)
Quantity	1
Fire & Safety Assessor	Kevin Jones GIFireE
Enforcing Fire Authority	Cleveland
Scheme Tel. No	
Other staff in attendance	None
Number of on-site Accent staff	Scheme Manager Weekdays
Number of other (non-Accent) staff	Contract Cleaners in common areas
Scheme Inspection completed	Yes
Number of occupants	10
Personal Emergency Evacuation Plans in place	N/A
Current Evacuation Strategy	Full (Simultaneous) Evacuation
Conversion or purpose-built	Purpose Built
Number of Storeys	1
Number of floors on which car parking is provided	1
Is there a habitable basement?	No
No. of internal staircases (protected/unprotected)	none
Number of external staircases	None
External balcony part of escape route?	No
Unusual features	None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade	Vehicular Access to one or more elevations
Surroundings: Residential/Commercial	Light Commercial
Fire Detection and Warning System	Common areas only
Grade of Fire Alarm	Grade A
Category of Fire Alarm	LD1 Maximum Protection
Emergency Lighting Provision	Mixed system - Common areas
Portable Fire Extinguishers / Fire Blankets supplied / fitted	Yes
Water Extinguisher(s) present	Yes
Foam Extinguisher(s) present	No
Dry Powder Extinguisher(s) present	No
Carbon Dioxide Extinguisher(s) present	Yes
Fire Blanket(s) present	Yes
Fixed Fire Fighting Installations supplied / fitted	No
Dry Riser(s) present	No
Wet Riser(s) present	No
Sprinkler System present	No
Hosereel(s) present	No
Automatic Opening Vent(s) present	No

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no obvious damage?	Yes
Comment	All appear in good condition and secured
Valid Electrical Installation Condition Reports held on file? (Common Areas & General Needs Flats)	Yes
Comment	Landlord responsible for electrical inspections
Electrical App/PA Testing - tested within past 12 months?	Yes
Comment	Last tested 03/2025
Absence of trailing leads and adapters?	Yes
Comment	All leads secured and stored correctly
Evidence that mobility scooters are not being stored/charged in common areas?	No
Comment	
Is there a purpose built mobility scooter store/charging area?	N/A

Comment

Does the building have a lightning protection system?

No

Comment

Not required for the height of building

Gas installations

Is there a commercial/domestic gas supply to the scheme?

Yes

Comment

Commercial supply to heating boilers

Valid LGSR held on file for fixed communal area gas appliances?
(Boilers)

Yes

Comment

Next inspection due 26/09/2026

Valid LGSR held on file for residential flats that contains gas appliances?

N/A

Comment

No flats this is an office building only

Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results

N/A

Comment

Observation	Priority	Referred To	Required By:	Task ID
Gas intake cupboard clear of combustible materials	No Action			



Other Sources of Ignition

Is there a no smoking policy in place, which is enforced and adhered to?

Yes

Comment

No smoking throughout the property

Adequate security against arson?

Yes

Comment

Fob entry into main entrance

Are refuse/recycling bin areas managed and suitably located?

Yes

Comment

Dedicated refuse store area away from building

Are there communal cooking facilities at this scheme?

Yes


Comment

Very small kitchen area for warming food and hot drinks

Are reasonable measures taken to prevent fires as a result of cooking?	Yes
Comment	Kettle and microwave supplied and tested regularly
Where there is extraction in communal kitchens, are filters and ductwork changed/cleaned regularly?	N/A
Comment	No cooking appliance present

Housekeeping

Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and residents personal items?	Yes
Comment	Gas intake cupboard only clear of all unnecessary materials
Are unnecessary accumulations of combustible materials or waste avoided?	No
Comment	Sterile
Are combustible materials and substances separated from ignition sources and stored appropriately?	No
Comment	Excessive combustible materials stored in office area. Email sent to manager 30/11/205 for removal and management
Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?	Yes
Comment	

Observation	Priority	Referred To	Required By:	Task ID
Excessive fire loading, cardboard stored in office area	Internal - Medium			


Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?	Yes
Comment	

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of escape in case of fire?	Yes
---	-----

Asset ID:	33965	Trident House Falcon Court, Stockton on Tees
Comment	Two directional MOE	
Escape routes unobstructed and safe to use?	Yes	
Comment	Clear escape routes identified during assessment	
Exits immediately openable without a key and/or failsafe's function correctly?	Yes	
Comment	Electrical exit button and card swipe	
Reasonable distances of travel where there is a single/alternative direction of travel?	Yes	
Comment	Minimal travel distances observed	
Escape routes lead to final exits and open in direction of escape where necessary?	Yes	
Comment		

Observation	Priority	Referred To	Required By:	Task ID
Exit doors operated with out keys	No Action			

Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?	Yes
Comment	Traditional construction Brick and mortar , plaster finish and concrete floors.
Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?	Yes
Comment	Plaster finished walls and concrete ceiling and floors
Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?	N/A
Comment	None provided
As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?	N/A
Comment	Unable to access roof space no access from office area.
Loft hatches fire resisting?	N/A
Comment	

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?	N/A
Comment	No cross corridors in office area
Do external walls, doors, windows and anything attached to the exterior, limit fire spread?	No
Comment	
If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available?	N/A
Comment	None fitted
Are roller shutter doors that are required to be FR, fire resisting and self-closing?	N/A
Comment	None fitted

Observation	Priority	Referred To	Required By:	Task ID
Small kitchen area	No Action			
				

Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per current standards?	Yes
Comment	Lighting appears to be installed to meet the current standard
Emergency lighting units in good condition and securely fixed to walls/ceilings?	Yes
Comment	All appear to be in good condition and secure
Records of monthly/annual testing available?	Yes
Comment	Last tested 28/06/2025

Observation	Priority	Referred To	Required By:	Task ID
Mixed emergency lighting	No Action			

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent locations within the common areas?	Yes
Comment	
Directional fire escape signage in place and adequate?	Yes
Comment	
Is there suitable LIFT signage i.e. do not use in case of fire?	Yes
Comment	Lift inoperable during assessment
Do common area fire doors display the correct signage on both sides where applicable?	Yes
Comment	

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?	Yes
Comment	
Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?	Yes
Comment	
Is the fire detection and warning system maintained/tested and all certificates saved on file?	Yes
Comment	Last tested 26/01/2025
Fire alarm components in good condition and securely fixed to walls/ceilings?	Yes
Comment	All appear in good condition and secure
Hold open devices operate at the sounding of the alarm and are in a serviceable condition?	N/A
Comment	None fitted

Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?	Yes
Comment	Electrical intake cupboard in communal area.
Is the fire alarm panel remotely monitored, and if so are there records of regular testing?	No
Comment	

Observation	Priority	Referred To	Required By:	Task ID
Fire detection system in good condition and secured	No Action			
				

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?	Yes
Comment	
Portable fire extinguishers - appropriate type/number/position?	Yes
Comment	
Correct signage displayed by each fire extinguisher?	Yes
Comment	
Fire blanket in communal kitchen, secured to the wall, complete with signage?	Yes
Comment	
Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to outlet valves?	N/A
Comment	None fitted
Records available of fire fighting equipment servicing within past 12 months?	Yes
Comment	Last tested 03/2025

Observation

Priority


Referred To

Required By:

Task ID

Fire extinguishers test up to date and positioned correctly with signage

No Action



Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?

No

Comment

Are there other Responsible Persons who share or have fire safety duties in respect of the premises?

Yes

Have all details required by regulations been shared with all other Responsible Persons?

Yes

Comment

Have all details required by regulations to be shared with us from other Responsible Persons been received and recorded?

Yes

Comment

Will this FRA be shared with all other Responsible Persons for the premises?

Yes

Comment

How will this sharing be achieved?

Emailed to landlord

Is an office or IL scheme being inspected?

Yes

Comment

IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens?

N/A

Comment

Due to hybrid working no designated fire warden training to all Accent staff in fire awareness and from fire risk assessor.

Offices - Are there suitable arrangements for ensuring the premises are evacuated?

Yes

Comment

Offices - Are there suitable arrangements for evacuating disabled people?

Yes

Comment

Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information?	Yes
Comment	Member of the office team will meet fire service
Offices/IL Schemes - Is there a suitable assembly point?	Yes
Comment	Car park opposite the office building
Offices - Are fire drills carried out at appropriate intervals?	No
Comment	Training provided periodically

Passenger Lift

Is the scheme fitted with a passenger lift?	Yes
Comment	
Is the lift in full working order at the time of the FRA?	No
Comment	Not working during assessment
Is the lift fitted with a firefighters switch?	No
Comment	
Servicing and insurance inspection - Evidence of regular servicing/maintenance?	N/A
Comment	Landlord responsible for lift maintenance

Premises Inspection Box

Is there a premises information box for fire & rescue service use?	No
Comment	Not required for office

Evacuation Policy

Are there suitable arrangements for summoning the fire service?	Yes
Comment	999 call from occupants
Taking FRA findings, is the evacuation policy appropriate for the scheme as per latest guidance?	Yes
Comment	

Engagement with Residents

Has information of fire procedures been disseminated to residents?	Yes
Comment	Fire awareness training and office fire awareness training provided periodically.
Is general fire safety information disseminated to residents?	N/A

Comment

No residence office area only

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Yes

Comment

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

No

Are there fire related remedial works required at this property, that will affect the fabric of the building?

No

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW



MEDIUM



HIGH



2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

MINOR



MAJOR



CRITICAL



The definition of the above terms is as follows:

FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trivial	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:

Trivial