Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 132 Harrison Court, Nottingham

Cover Sheet

Photo

Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor



15 May 2025

15 May 2026

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Lynn.betteridge GIFire (Dip)NEBOSH

This assessment covers only the community room and laundry areas as all flats have their own acess/egress and do not fall under the fire safety order 2005.

The Scheme

Scheme Name Harrison Court

Scheme Address Harrison Court, Nottingham

Postcode NG13 8TD

Region East

Scheme Manager

Scheme Tel. No This scheme has no office contact.

Scheme Inspection Completed Yes

Enforcing Fire Authority Nottinghamshire Fire and rescue service.

Other staff in attendance No staff on this scheme.

Number of on-site Accent staff None

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type Non Social Leasehold (S60), Shared Ownership

(S40)

Build Date Jan 1 1990

Number Of Homes 37

Homes breakdown Bungalow, Flat

External wall construction Facing Brick

External wall finish Facing Brick, Timber Clad

Roof construction Timber

Roof covering Interlocking Pitched

PEEPs in place where necessary N/A

Current Evacuation Strategy Full (Simultaneous) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 2

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?)

None

Number of External Staircases None

External Balcony part of escape route?

Unusual features

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Harrison Court, Nottingham Asset ID: 132 Fire Detection and Warning System Common areas only Grade D Grade of fire alarm Category of fire alarm LD3 Minimum Protection **Emergency Lighting Provision** Non Maintained System - Common Areas Portable Fire Extinguishers supplied/fitted Yes Fixed Fire Fighting Installations No **Customers** 33 Number of occupants Non Social Leasehold, Staff Accommodation Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 0 0 Overdue Annual Emergency Lighting tests Overdue Weekly Fire Alarm Testing 0 Overdue Fire Panel - Six Monthly Testing 3 Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 0 **Dwelling Doors** Failing Dwelling Fire Doors 0

Dwelling Fire doors due for replacement within 5 years

0

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

Enforcing Fire Authority

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

Current Evacuation Strategy

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

13/05/2024

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

1

Lynn.betteridge GIFire (Dip)NEBOSH

This assessment covers only the community room and laundry areas as all flats have their own acess/egress and do not fall under the fire safety order 2005.

Nottinghamshire Fire and rescue service.

This scheme has no office contact.

No staff on this scheme.

None

Contract Cleaners in common areas

Yes

33

N/A

Full (Simultaneous) Evacuation

Purpose Built

2

0

No

None

Fire Risk Assessment Survey Results

None Number of external staircases

External balcony part of escape route? No

Unusual features

Vehicular Access to one or more elevations Building access conditions for Fire Brigade

Surroundings: Residential/Commercial Residential

Common areas only Fire Detection and Warning System

Grade of Fire Alarm Grade D

LD3 Minimum Protection Category of Fire Alarm

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted Yes

Yes Water Extinguisher(s) present

Foam Extinguisher(s) present No

Dry Powder Extinguisher(s) present No

Carbon Dioxide Extinguisher(s) present Yes

No Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted No

No Dry Riser(s) present

Wet Riser(s) present No

Sprinkler System present No

Hosereel(s) present No

No Automatic Opening Vent(s) present

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no

obvious damage?

Comment On the day of inspection the electrical installations

in the community area were found to be in good

working condition.

Yes

Yes

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment The community area block has an in date Electrical certificate which is uploaded to Active"H"and M files

Database. Community area tested 9/1/2024.

Yes

Electrical App/PA Testing - tested within past 12 months?

Comment

Harrison Court, Nottingham Asset ID: 132 Absence of trailing leads and adapters? Yes Comment No evidence of trailing leads within the communal Evidence that mobility scooters are not being stored/charged in Yes common areas? Comment There was no visible signs of mobility scooter use on scheme. Is there a purpose built mobility scooter store/charging area? No Comment No Does the building have a lightning protection system? Comment Gas installations No Is there a commercial/domestic gas supply to the scheme? Comment Other Sources of Ignition Is there a no smoking policy in place, which is enforced and adhered Yes to? Comment Communal areas of scheme are designated no smoking and residents are made aware of the policy and enforced. Yes Adequate security against arson? Comment All doors secure on the scheme at the time of inspection. Are refuse/recycling bin areas managed and suitably located? Yes Comment Are there communal cooking facilities at this scheme? No Comment Housekeeping Yes Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items? Comment Yes Are unnecessary accumulations of combustible materials or waste avoided? Comment Are combustible materials and substances separated from ignition Yes

sources and stored appropriately?

Asset ID: 132 **Harrison Court, Nottingham** Comment Yes Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations? Comment Fire retardant labels attached to the furniture in the community area at the time of inspection. Other Significant Fire Hazards Are all other significant fire hazards adequately controlled? Yes Comment The scheme is a very clean and managed well.All flats have there own access door. The scheme has a laundry room and dryers all machines are maintained annually and a contract includes lint removal. Residents are reminded to remove lint monthly and signage in place. Means of Escape from Fire Is it considered that the building is provided with reasonable means of Yes escape in case of fire? Comment Escape routes unobstructed and safe to use? Yes Comment Each flat has its own access door communal area building has a "simultaneous "evacuation policy and the residents have been made aware and that they proceed to the assembly point. Yes Exits immediately openable without a key and/or failsafe's function correctly? Comment Communal scheme area only. Yes Reasonable distances of travel where there is a single/alternative direction of travel? Comment Escape routes lead to final exits and open in direction of escape where necessary? Comment Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect means of escape against fire, smoke and combustion products?

Yes

Yes

N/A

Asset ID: 132 **Harrison Court, Nottingham** Comment Yes As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard? Comment Loft hatches fire resisting? N/A Comment As far as can be reasonably ascertained, is the fire stopping above Yes cross corridor fire doors within suspended ceiling void of a satisfactory standard? Comment Yes Do external walls, doors, windows and anything attached to the exterior, limit fire spread? Comment The external walls doors and windows will not propagate fire spread around the envelope of the building this includes blocks and community area. N/A If Smoke Control Systems (AOV's) are fitted, are the records of annual testing available? Comment Are roller shutter doors that are required to be FR, fire resisting and N/A self-closing? Comment **Emergency Escape Lighting** Yes Is the emergency lighting correctly specified and installed as per current standards? Comment The scheme community area has had a complete refit of the emergency lighting system to include toilet area and the maintained system meets the approved specification BS5266-1. Work completed 8/6/2024. Yes Emergency lighting units in good condition and securely fixed to walls/ceilings? Comment Yes Records of monthly/annual testing available? Comment The emergency lighting system at this scheme has been tested monthly on the 28/4/2025 and the annual drop test was completed on 27/9/2024.

Observation Priority Referred To Required By: Task ID

New complete emergency lighting system installed.

No Action





Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

locations within the common areas?

Directional fire escape signage in place and adequate?

Comment

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

Comment

Do common area fire doors display the correct signage on both sides

where applicable?

Comment

Yes

All relevant signage is provided at each exit and in

other areas.

Yes

N/A

Yes

Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Yes

Comment Only in community area which smoke detectors are

linked to Warden call system calls go to the

collecting station Astraline.

Is fire detection and warning system appropriate for occupancy and fire

risk, as per BS 5839-1:2017?

Comment

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Comment

Fire alarm components in good condition and securely fixed to

walls/ceilings?

Comment

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Yes

Yes

Yes

N/A

Harrison Court, Nottingham	
ed in the Kitchen, Boiler, Plant Room and	Yes
y monitored, and if so are there records of	N/A No fire panel on this scheme all detectors .inked to Warden call and Astraline tested weekly by tunstalls.
uipment	
t and/or fixed fire fighting installations	Yes
propriate type/number/position?	Yes
each fire extinguisher?	Yes
en, secured to the wall, complete with	No
	There is no communal kitchen on this scheme.
secured and/or securing straps fitted to	N/A
ng equipment servicing within past 12	Yes
	The fire extinguishers are tested annually by Morgan Fire recorded test date 66/2024.
afety	
by the Building Safety Regulator under	No
ersons who share or have fire safety es? ved?	No
inspected?	
s - Are there sufficient numbers of	N/A
	with the Kitchen, Boiler, Plant Room and with monitored, and if so are there records of and/or fixed fire fighting installations propriate type/number/position? Each fire extinguisher? en, secured to the wall, complete with ecured and/or securing straps fitted to ag equipment servicing within past 12 afety by the Building Safety Regulator under ersons who share or have fire safety es? eved? inspected?

Harrison Court, Nottingham Asset ID: 132 Comment This scheme does not benefit from having a scheme manger on site. Yes Offices - Are there suitable arrangements for ensuring the premises are evacuated? Comment Yes Offices - Are there suitable arrangements for evacuating disabled people? Comment A PEEPS personal centred fire risk assessment is completed for all residents. N/A Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information? Comment Offices/IL Schemes - Is there a suitable assembly point? Yes Comment Offices - Are fire drills carried out at appropriate intervals? No Comment Passenger Lift Is the scheme fitted with a passenger lift? No Comment **Premises Inspection Box** Is there a premises information box for fire & rescue service use? No Comment **Evacuation Policy** Are there suitable arrangements for summoning the fire service?

Comment Warden call system linked to laundry and

community room direct to Astraline collecting

station.

Yes Taking FRA findings, is the evacuation policy appropriate for the

scheme as per latest guidance?

Comment The FRA is for the community room and laundry

and simultaneous evacuation.

Engagement with Residents

Yes Has information of fire procedures been disseminated to residents?

Comment

When residents move into the flats they are given fire safety advice and also leaflets and a link into the website to look at the FRA the details will be shared and communicated on request. The residents are given contact details of the area fire safety assessor.

Is general fire safety information disseminated to residents?

Yes

Comment

Fire routine notices are located at all exit points. During the year campaigns are communicated on fire safety themes.

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Comment

Yes

Miscellaneous

Are there any other observations/actions to raise that are not covered above.

Are there fire related remedial works required at this property, that will affect the fabric of the building?

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

No

No

No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

1. Taking into account the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from the fire (the probability of ignition) at this building is:

LOW

MEDIUM

HIGH

2. Taking into account the nature of the building, the occupants, the fire protection afforded and any procedural arrangements observed at the time of the assessment, it is considered that the consequences for life safety in the event of a fire would be:

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).	
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.	
CRITICAL	There is significant potential for serious injury or death of one or more occupants.	

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>