# Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 24574 Derek Horn Court

#### **Cover Sheet**

Photo

14 Apr 2025

14 Apr 2026

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Gary Bredin AlFireE

Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Derek Horn Court

Scheme Address Derek Horn Court

Postcode GU15 3JL

Region South

Scheme Manager

Scheme Tel. No

Scheme Inspection Completed Yes

Enforcing Fire Authority Surrey Fire and Rescue service

Other staff in attendance Lorraine Linman

Number of on-site Accent staff Scheme Manager Weekdays

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type CAT2 Housing for Older People (S28)

Build Date Jan 1 1990

Number Of Homes 34

Homes breakdown Flat

External wall construction Facing Brick

External wall finish Cement Render, Facing Brick, Timber Clad

Roof construction Timber

Roof covering Interlocking Pitched

PEEPs in place where necessary

Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys 1, 3

Number of floors on which car parking is provided 0

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?) 3 Protected

Number of External Staircases None

External Balcony part of escape route? N/A

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

**Derek Horn Court** Asset ID: 24574 Fire Detection and Warning System Flats and common areas linked Grade A Grade of fire alarm Category of fire alarm LD2 Additional Protection **Emergency Lighting Provision** Non Maintained System - Common Areas Portable Fire Extinguishers supplied/fitted Yes Fixed Fire Fighting Installations No **Customers** 50 Number of occupants CAT2 Housing for Older People, Sheltered Schemes Occupant tenure type breakdown Fire Safety Related Customer Safety Servicing Overdue communal gas safety checks 0 0 Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 Overdue communal PAT testing 0 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 0 Overdue Annual Emergency Lighting tests Overdue Weekly Fire Alarm Testing 1 Overdue Fire Panel - Six Monthly Testing 1 Overdue Fire Safety Equipment tests 1 **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors Communal Fire doors due for replacement within 5 years 63 **Dwelling Doors** 0 Failing Dwelling Fire Doors

Dwelling Fire doors due for replacement within 5 years

0

# Fire Risk Assessment Survey Results

#### **Scheme and Building Information**

Photo



Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

**Enforcing Fire Authority** 

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

**Current Evacuation Strategy** 

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

14/04/2025

12

**Annual Re-Assessment** 

Type 1 (Common Parts Only - Non Destructive)

1

Gary Bredin AlFireE

Surrey Fire and Rescue service

Lorraine Linman

Scheme Manager Weekdays

Contract Cleaners in common areas

Yes

50

Yes

Stay Put (Delayed) Evacuation

Purpose Built

3

0

No

3 Protected

None

N/A

None

# Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Vehicular Access to one or more elevations

Surroundings: Residential/Commercial Residential

Fire Detection and Warning System Flats and common areas linked

Grade of Fire Alarm Grade A

Category of Fire Alarm LD2 Additional Protection

Emergency Lighting Provision Non Maintained System - Common Areas

Portable Fire Extinguishers / Fire Blankets supplied / fitted Yes

Water Extinguisher(s) present

Foam Extinguisher(s) present Yes

Dry Powder Extinguisher(s) present No

Carbon Dioxide Extinguisher(s) present Yes

Fire Blanket(s) present Yes

Fixed Fire Fighting Installations supplied / fitted No

Dry Riser(s) present No

Wet Riser(s) present

Sprinkler System present No

Hosereel(s) present No

Automatic Opening Vent(s) present No

#### **Electrical Sources of Ignition**

Electrical installation within common areas in good condition and no

obvious damage?

Comment

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Last test April 2022

Electrical App/PA Testing - tested within past 12 months?

Yes

Comment Last test December 2024

Absence of trailing leads and adapters? Yes

Comment

Evidence that mobility scooters are not being stored/charged in Yes

common areas?

Comment

Is there a purpose built mobility scooter store/charging area?

Yes

Yes

**Derek Horn Court** Asset ID: 24574 Comment N/A Does the building have a lightning protection system? Comment N/A Is the protection system adequately maintained? Comment Gas installations Is there a commercial/domestic gas supply to the scheme? Yes Comment Yes Valid LGSR held on file for fixed communal area gas appliances? (Boilers) Comment Yes Valid LGSR held on file for residential flats that contains gas appliances? Comment Last test July 2024 Yes Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results Comment Other Sources of Ignition Yes Is there a no smoking policy in place, which is enforced and adhered Comment Yes Adequate security against arson? Comment Electronic door entry system in place Yes Are refuse/recycling bin areas managed and suitably located? Comment All clear at the time of the audit Are there communal cooking facilities at this scheme? Yes Comment Are reasonable measures taken to prevent fires as a result of cooking? Yes Comment Yes Where there is extraction in communal kitchens, are filters and ductwork changed/cleaned regularly?

#### Housekeeping

Comment

Asset ID: 24574 Derek Horn Court	
Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?  Comment	Yes
Are unnecessary accumulations of combustible materials or waste avoided?  Comment	Yes
Are combustible materials and substances separated from ignition sources and stored appropriately?  Comment	N/A
Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?  Comment	Yes
Other Significant Fire Hazards	
Are all other significant fire hazards adequately controlled?	Yes
Comment	
Means of Escape from Fire	
Is it considered that the building is provided with reasonable means of escape in case of fire?  Comment	Yes
Escape routes unobstructed and safe to use?	Yes
Comment	
Exits immediately openable without a key and/or failsafe's function correctly?	Yes
Comment	
Reasonable distances of travel where there is a single/alternative direction of travel?  Comment	Yes
Escape routes lead to final exits and open in direction of escape where necessary?	Yes

Comment

Observation Priority Referred To Required By: Task ID

All areas were clear at the time of the audit.





#### **Fire Spread and Development**

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect
means of escape against fire, smoke and combustion products?

Yes

Comment

As far as can be reasonably ascertained, is the compartmentation within roof spaces of a satisfactory standard?

Comment This area was not checked during the audit

Yes

N/A

N/A

Loft hatches fire resisting?

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Comment

Do external walls, doors, windows and anything attached to the

exterior, limit fire spread?

If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available?

Comment

Comment

Are roller shutter doors that are required to be FR, fire resisting and

self-closing?

Comment

Observation Priority Referred To Required By: Task ID

All furniture checked complies to the latest standards





Observation Priority Referred To Required By: Task ID

Bin area clear at the time of the audit.





Yes

#### **Emergency Escape Lighting**

Is the emergency lighting correctly specified and installed as per current standards?

Comment

Emergency lighting units in good condition and securely fixed to Yes walls/ceilings?

Comment

Records of monthly/annual testing available?

Comment Last drop test April 2025

## **Fire Safety Signs and Notices**

Are the correct Fire Action/Advice notices displayed in prominent

Yes

locations within the common areas?

Comment

Directional fire escape signage in place and adequate?

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

Asset ID: 24574 Derek Horn Court	
Comment	
Do common area fire doors display the correct signage on both sides where applicable?  Comment	Yes
Means of giving Warning in case of Fire	
Is the scheme fitted with a communal area fire alarm?	Yes
Comment	
Is fire detection and warning system appropriate for occupancy and fire risk, as per BS 5839-1:2017?  Comment	Yes
Is the fire detection and warning system maintained/tested and all certificates saved on file?  Comment	Yes
Fire alarm components in good condition and securely fixed to walls/ceilings?  Comment	Yes
Hold open devices operate at the sounding of the alarm and are in a serviceable condition?  Comment	Yes
Are there heat detectors located in the Kitchen, Boiler, Plant Room and Laundry?  Comment	Yes
Is the fire alarm panel remotely monitored, and if so are there records of regular testing?	Yes
Comment	Out of hours monitoring service
Fire Extinguishing Equipment	
Is fire extinguishing equipment and/or fixed fire fighting installations provided at this scheme?  Comment	Yes
Portable fire extinguishers - appropriate type/number/position?	Yes
Comment	
Correct signage displayed by each fire extinguisher?	Yes
Comment	
Fire blanket in communal kitchen, secured to the wall, complete with signage?  Comment	Yes
Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to outlet valves?	N/A

Page 10 of 15

MIS-AMS ActiveH - Fire Risk Assessment Report

Generated 14/04/2025 16:02:44

**Derek Horn Court** Asset ID: 24574

Comment

Records available of fire fighting equipment servicing within past 12

months?

Comment

Observation **Priority** Referred To Required By: Task ID

Yes

Yes

All fire extinguishers werebinbthere correct location and in test date.





#### Management of Fire Safety

No Are these premises regulated by the Building Safety Regulator under

Comment

Comment

Comment

Comment

Comment

Comment

Yes Are there other Responsible Persons who share or have fire safety

duties in respect of the premises?

Yes Have all details required by regulations been shared with all other

Responsible Persons?

the Building Safety Act?

Responsible Persons been received and recorded?

Yes Will this FRA be shared will all other Responsible Persons for the

premises?

Have all details required by regulations to be shared with us from other

This is available on request How will this sharing be achieved?

Yes

Is an office or IL scheme being inspected?

Yes IL Schemes & Regional Offices - Are there sufficient numbers of

qualified Fire wardens?

Comment

Offices - Are there suitable arrangements for ensuring the premises are Yes

evacuated?

MIS-AMS ActiveH - Fire Risk Assessment Report

Page 11 of 15

Generated 14/04/2025 16:02:44

Asset ID:	24574	Derek Horn Court	
Offices - Are people? Comment	there suitable arr	rangements for evacuating disabled	Yes
	table arrangemen relevant informati	ts for meeting the fire service on arrival on?	Yes
Offices/IL Sc	chemes - Is there	a suitable assembly point?	Yes
Comment			
Offices - Are	fire drills carried	out at appropriate intervals?	Yes
Comment			
Passenge	er Lift		
Is the schem	ne fitted with a pas	ssenger lift?	Yes
Comment			
Is the lift in fu	ull working order a	at the time of the FRA?	Yes
Comment			
Is the lift fitte	ed with a firefighte	rs switch?	No
Comment			
Servicing and servicing/ma		ction - Evidence of regular	Yes
Comment			Last test January 2025
Premises	Inspection E	Box	
Is there a pre	emises informatio	n box for fire & rescue service use?	No
Comment			
Evacuation	on Policy		
Are there sui	itable arrangemer	nts for summoning the fire service?	Yes
Comment			
	findings, is the event	acuation policy appropriate for the e?	Yes

Observation Priority Referred To Required By: Task ID

Evacuation policy posted throughout the building





#### **Engagement with Residents**

Has information of fire procedures been disseminated to residents?

Comment

Is general fire safety information disseminated to residents?

Yes

Comment

## **FRA Frequency**

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Comment

#### Miscellaneous

Are there any other observations/actions to raise that are not covered Yes

above.

Comment

Action leading to a repair Yes

Internal administrative Action Yes

Are there fire related remedial works required at this property, that will

affect the fabric of the building?

Were there any unsatisfactory aspects of the Fire Risk Assessment?

(Visible on Building Safety Report).

No

#### **Risk Calculator - Fire**

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.					
1	•	evention measures of the hazard from the			t this
LOW	X	MEDIUM		нідн	
any procedural	arrangements ob	e of the building, the oserved at the time one event of a fire wo	of the assessme	•	
MINOR		MAJOR	X	CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).	
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.	
CRITICAL	There is significant potential for serious injury or death of one or more occupants.	

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales	
Trivial	No action is required	
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.	
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.	
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.	

The Overall Risk Level for this asset is:	Trivial