Fire Risk Assessment Report



This report shows all the responses to the Fire Risk Assessment survey, including raised tasks.

Asset ID: 24570 Ballard Court

Cover Sheet

Photo

20 Mar 2025

20 Mar 2026

12

Annual Re-Assessment

Type 1 (Common Parts Only - Non Destructive)

Gary Bredin AlFireE

Date of Fire Risk Assessment

Date of Next Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Fire Risk Assessment

Fire & Safety Assessor

It is sensible to have arrangements in place to ensure the consistency of Fire Risk Assessments in terms of the assessment of risk and mitigations proposed. In this regard Accent peer validate around 20% of reports, which are available within our audit system.

The Scheme

Scheme Name Ballard Court

Scheme Address Ballard Court

Postcode

Region South

Scheme Manager

Scheme Tel. No -

Scheme Inspection Completed Yes

Enforcing Fire Authority Surrey Fire and Rescue service

Other staff in attendance None

Number of on-site Accent staff Scheme Manager Weekdays

Number of other (non-Accent) staff

Contract Cleaners in common areas

The Building

Accommodation Type CAT2 Housing for Older People (S28)

Build Date Jan 1 1967

Number Of Homes 82

Homes breakdown Bedsit, Bungalow, Flat

External wall construction Facing Brick

External wall finish Facing Brick, Timber Clad

Roof construction Timber

Roof covering Flat Roof, Interlocking Pitched

PEEPs in place where necessary

Yes

Current Evacuation Strategy Stay Put (Delayed) Evacuation

Conversion or purpose-built Purpose Built

Number of storeys

Number of floors on which car parking is provided 2

Is there a habitable basement?

Number of internal Staircases (protected or unprotected?) 4 Protected

Number of External Staircases 1 not a destination fire escape.

External Balcony part of escape route? N/A

Unusual features None

Building Access Conditions for Fire Brigade

Vehicular Access to one or more elevations

Asset ID: 24570 Fire Detection and Warning System Flats and common areas not linked Grade D Grade of fire alarm Category of fire alarm **LD1 Maximum Protection** Non Maintained System - Common Areas **Emergency Lighting Provision** Portable Fire Extinguishers supplied/fitted Yes Fixed Fire Fighting Installations No **Customers** 50 Number of occupants Occupant tenure type breakdown CAT1 Housing for Older People, CAT2 Housing for Older People, General Needs, Sheltered Schemes Fire Safety Related Customer Safety Servicing 0 Overdue communal gas safety checks Overdue domestic gas safety checks 0 Overdue communal electrical condition checks 0 0 Overdue domestic electrical condition checks Overdue alarm call pull chord tests 0 0 Overdue communal PAT testing 0 Overdue customer mobility scooter PAT testing Overdue Monthly Emergency Lighting Switch Tests 0 0 Overdue Annual Emergency Lighting tests Overdue Weekly Fire Alarm Testing 1 9 Overdue Fire Panel - Six Monthly Testing 9 Overdue Fire Safety Equipment tests **Building Fire Safety Surveys - Communal Doors** 0 Failing Communal Fire Doors 0 Communal Fire doors due for replacement within 5 years **Dwelling Doors** 0 Failing Dwelling Fire Doors 0 Dwelling Fire doors due for replacement within 5 years

Ballard Court

Fire Risk Assessment Survey Results

Scheme and Building Information

Photo

20/03/2025

12

Date of Fire Risk Assessment

FRA Frequency (Months)

Purpose of Fire Risk Assessment

Type of Risk Assessment

Quantity

Fire & Safety Assessor

Enforcing Fire Authority

Scheme Tel. No

Other staff in attendance

Number of on-site Accent staff

Number of other (non-Accent) staff

Scheme Inspection completed

Number of occupants

Personal Emergency Evacuation Plans in place

Current Evacuation Strategy

Conversion or purpose-built

Number of Storeys

Number of floors on which car parking is provided

Is there a habitable basement?

No. of internal staircases (protected/unprotected)

Number of external staircases

External balcony part of escape route?

Unusual features

Gary Bredin AlFireE

Surrey Fire and Rescue service

-

None

Fire Risk Assessment Survey Results

Building access conditions for Fire Brigade

Surroundings: Residential/Commercial

Fire Detection and Warning System

Grade of Fire Alarm

Category of Fire Alarm

Emergency Lighting Provision

Portable Fire Extinguishers / Fire Blankets supplied / fitted

Water Extinguisher(s) present

Foam Extinguisher(s) present

Dry Powder Extinguisher(s) present

Carbon Dioxide Extinguisher(s) present

Fire Blanket(s) present

Fixed Fire Fighting Installations supplied / fitted

Dry Riser(s) present

Wet Riser(s) present

Sprinkler System present

Hosereel(s) present

Automatic Opening Vent(s) present

Electrical Sources of Ignition

Electrical installation within common areas in good condition and no obvious damage?

Comment

Valid Electrical Installation Condition Reports held on file? (Common

Areas & General Needs Flats)

Comment Next test June 2025

Electrical App/PA Testing - tested within past 12 months?

Yes

Comment

Absence of trailing leads and adapters?

Comment

Comment

Evidence that mobility scooters are not being stored/charged in Yes

common areas?

Is there a purpose built mobility scooter store/charging area?

Yes

Yes

Asset ID: 24570 Ballard Court	
Comment	
Does the building have a lightning protection system?	No
Comment	
Gas installations	
Is there a commercial/domestic gas supply to the scheme?	Yes
Comment	
Valid LGSR held on file for fixed communal area gas appliances? (Boilers) Comment	Yes
Valid LGSR held on file for residential flats that contains gas appliances?	No
Comment	No gas supply to flats
Are smoke/heat detectors within General Needs flats subject to an annual inspection and the results	Yes
Comment	
Other Sources of Ignition	
Is there a no smoking policy in place, which is enforced and adhered to?	Yes
Comment	
Adequate security against arson?	Yes
Comment	Electronic entry system in place
Are refuse/recycling bin areas managed and suitably located?	Yes
Comment	
Are there communal cooking facilities at this scheme?	Yes
Comment	
Are reasonable measures taken to prevent fires as a result of cooking?	Yes
Comment	
Where there is extraction in communal kitchens, are filters and ductwork changed/cleaned regularly?	Yes
Comment	
Housekeeping	
Are all electrical/intake/service cupboards secure and free from general waste, contractors waste and and residents personal items?	Yes
Comment	All electrical cupboards were clear at the time of the audit

Page 6 of 15

Generated 20/03/2025 16:03:06

MIS-AMS ActiveH - Fire Risk Assessment Report

Are unnecessary accumulations of combustible materials or waste

avoided?

Comment

Are combustible materials and substances separated from ignition

sources and stored appropriately?

Comment

Furniture/furnishings in good condition, fire retardant/resistant and comply with modern standards and regulations?

Comment

Yes

Yes

N/A

Observation Priority Referred To Required By: Task ID

All tumble dryers were clear and filters empty.



Other Significant Fire Hazards

Are all other significant fire hazards adequately controlled?

Comment

Yes

Means of Escape from Fire

Is it considered that the building is provided with reasonable means of

escape in case of fire?

Yes

Comment

Escape routes unobstructed and safe to use?

Yes

Comment

Exits immediately openable without a key and/or failsafe's function

correctly?

Yes

Comment

Reasonable distances of travel where there is a single/alternative

direction of travel?

Yes

Comment

Escape routes lead to final exits and open in direction of escape where

necessary?

Comment

Observation Priority Referred To Required By: Task ID

All areas were clear at the time of the audit.





Fire Spread and Development

Is it considered that the compartmentation is of a reasonable standard?

Comment

Is there reasonable limitation of surface finishes that might promote fire Spread (walls, floors, ceilings)?

Comment

Are fire dampers/shutters provided in ducts/refuse chutes to protect N/A means of escape against fire, smoke and combustion products?

Comment

As far as can be reasonably ascertained, is the compartmentation N/A within roof spaces of a satisfactory standard?

Comment This area not checked during the audit

Loft hatches fire resisting?

Comment

As far as can be reasonably ascertained, is the fire stopping above cross corridor fire doors within suspended ceiling void of a satisfactory standard?

Comment

Do external walls, doors, windows and anything attached to the

exterior, limit fire spread?
Comment

If Smoke Control Systems (AOV's) are fitted, are the records of annual

testing available?

Are roller shutter doors that are required to be FR, fire resisting and

self-closing?
Comment

Comment

N/A

Yes

Observation Priority Referred To Required By: Task ID

All furniture checked were compliant





Emergency Escape Lighting

Is the emergency lighting correctly specified and installed as per Yes

Comment

Comment

Comment

Emergency lighting units in good condition and securely fixed to Yes

walls/ceilings?

current standards?

Records of monthly/annual testing available?

Comment Next drop test March 2026

Fire Safety Signs and Notices

Are the correct Fire Action/Advice notices displayed in prominent

Yes

locations within the common areas?

Directional fire escape signage in place and adequate?

Yes

Comment

Is there suitable LIFT signage i.e. do not use in case of fire?

N/A

Do common area fire doors display the correct signage on both sides N/A

where applicable?

Comment

Comment

Observation Priority Referred To Required By: Task ID

Evacuation policy posted throughout the buildings





Means of giving Warning in case of Fire

Is the scheme fitted with a communal area fire alarm?

Yes

Comment

Is fire detection and warning system appropriate for occupancy and fire

Yes

risk, as per BS 5839-1:2017?

Comment

Comment

Is the fire detection and warning system maintained/tested and all

certificates saved on file?

Fire alarm components in good condition and securely fixed to Yes walls/ceilings?

Comment

Comment

Comment

Comment

Hold open devices operate at the sounding of the alarm and are in a

serviceable condition?

Are there heat detectors located in the Kitchen, Boiler, Plant Room and

Laundry?

Is the fire alarm panel remotely monitored, and if so are there records of

regular testing?

Fire Extinguishing Equipment

Is fire extinguishing equipment and/or fixed fire fighting installations Yes provided at this scheme?

Comment

Portable fire extinguishers - appropriate type/number/position? Yes

Comment

Yes

Correct signage displayed by each fire extinguisher?

Comment

Fire blanket in communal kitchen, secured to the wall, complete with

signage?

Comment

Dry risers - Inlet/outlet boxes secured and/or securing straps fitted to

outlet valves?

Comment

Records available of fire fighting equipment servicing within past 12

months?

Comment

Observation

Required By:

Task ID

Yes

N/A

Yes

Referred To

Priority

All extinguishers were in date.



Management of Fire Safety

Are these premises regulated by the Building Safety Regulator under the Building Safety Act?

Comment

Are there other Responsible Persons who share or have fire safety

Yes

duties in respect of the premises?

Have all details required by regulations been shared with all other N/A

Responsible Persons?

Comment

Have all details required by regulations to be shared with us from other Yes

Responsible Persons been received and recorded?

Comment

Will this FRA be shared will all other Responsible Persons for the Yes

premises?

Comment

How will this sharing be achieved?

This is available on request

Is an office or IL scheme being inspected?

Comment

Ballard Court Asset ID: 24570 Yes IL Schemes & Regional Offices - Are there sufficient numbers of qualified Fire wardens? Comment Yes Offices - Are there suitable arrangements for ensuring the premises are evacuated? Comment Yes Offices - Are there suitable arrangements for evacuating disabled people? Comment Yes Offices - Suitable arrangements for meeting the fire service on arrival and proving relevant information? During daytime hours Comment Offices/IL Schemes - Is there a suitable assembly point? Yes Comment Offices - Are fire drills carried out at appropriate intervals? N/A Comment Passenger Lift Yes Is the scheme fitted with a passenger lift? Comment Chair lifts. Is the lift in full working order at the time of the FRA? Comment Yes Is the lift fitted with a firefighters switch? N/A Comment Yes Servicing and insurance inspection - Evidence of regular servicing/maintenance? Comment **Premises Inspection Box** No Is there a premises information box for fire & rescue service use? Comment **Evacuation Policy** Are there suitable arrangements for summoning the fire service? Yes

scheme as per latest guidance?

Taking FRA findings, is the evacuation policy appropriate for the

Comment

Out of hours monitored by Astraline

Asset ID:	24570	Ballard Court
ASSELID.	27010	Danara Court

Comment

Engagement with Residents

Has information of fire procedures been disseminated to residents?

Comment

Is general fire safety information disseminated to residents?

Comment

FRA Frequency

Taking the findings of this assessment into account, is the frequency of the FRA correct?

Comment

Yes

Miscellaneous

Are there any other observations/actions to raise that are not covered No

above.

Are there fire related remedial works required at this property, that will

affect the fabric of the building?

Comment

Were there any unsatisfactory aspects of the Fire Risk Assessment? (Visible on Building Safety Report).

No

No

Risk Calculator - Fire

The following risk estimator is based on the general health and safety risk level estimator contained within BS 8800: 1996. Guide to occupational health and safety management systems.

systems.					
	·	evention measures o			at this
LOW	X	MEDIUM		HIGH	
any procedural	arrangements ob	of the building, the oserved at the time or ne event of a fire wou	f the assessm	•	
MINOR		MAJOR		CRITICAL	

The definition of the above terms is as follows: FRA Review Frequency

MINOR	Outbreak of fire is unlikely to result in serious injury or death of any occupant (other than the occupant sleeping in a bedroom in which a fire occurs).
MAJOR	An outbreak of fire could result in injury of one or more occupants, but is unlikely to lead to fatalities.
CRITICAL	There is significant potential for serious injury or death of one or more occupants.

3. The above estimates are then read into the following matrix table to give the overall risk level for the site:

Fire Hazard	Minor	Major	Critical
Low	Trival	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

When the level of risk is established, the action level can be read from the table below:

Risk Level	Guide to actions and appropriate timescales
Trivial	No action is required
Moderate	Efforts should be made to reduce the risk level and this should be carried out within the specified time periods.
Substantial	Considerable resources may have to be allocated to reduce the risk level. It may be necessary to limit the occupation of some parts until urgent remedial action is taken.
Intolerable	The building (or the relevant area) should not be occupied until the risk is reduced.

The Overall Risk Level for this asset is:	Trivial
	<u> </u>